

System Requirements

Jerome 431-X/631-X or Jerome 431-XE/631-XE:	with communication capabilities or the option board feature (instrument has a 25-pin “D” connector and related internal hardware and software)
Operating System:	Windows 98 Second Edition, ME, NT, 2000, or XP
Ports:	at least one free serial port one free USB port

Optional Equipment

Jerome data logger*	to capture data in portable sampling mode available separately (P/N 6100-0010) or included with JCS data logger kit (P/N Y990-0169)
---------------------	---

Part Numbers

Y990-0168	JCS software kit Includes: software (available on CD), USB hardware security key, user’s manual, interface cable, and cable adapter
Y990-0169	JCS data logger kit* Includes: software (available on CD), USB hardware security key, user’s manual, interface cable, cable adapter, and data logger
Y990-0170	JCS upgrade kit – available to current JCI users only Includes: software (available on CD), USB hardware security key, and user’s manual
700-0042	JCS user’s manual
990-0171	USB hardware security key

* The JCS software can program the Jerome data logger to initiate automatic sampling, trigger alarms and store data when it is attached to the instrument. The optional data logger is necessary for recording and storing data, and also enables automatic sampling without an attached computer when the instrument is being used for portable applications.



ARIZONA INSTRUMENT LLC

3375 N. Delaware Street, Chandler, AZ 85225 • (602) 470-1414 • (800) 528-7411 • www.azic.com

Exclusive Manufacturer of Computrac® Moisture Analyzers and Jerome® Toxic Gas Analyzers